


MSB 114 -- 39 of 93 seats in need of reupholstering





Writing table detached from seat (lying at front of room)

MSB 100 -- 24 of 41 seats in need of reupholstering

